



1207 S. Platte River Dr.
Denver, CO 80223

(720) 398-6070

Invoice #:0022398

Original Estimate #:

AUTOMOTIVE IMPORTS

1207 S PLATTE RIVER DR
DENVER, CO 80223-
Home:(720) 398-6070

2015 Mercedes Benz CIs400

V6-2996 3.0L DOHC
VIN : WDDLJ6HB7FA156533
Mileage In 51015 Out 51081
Trans :
License : 0
Colr : **1/15/19**
Prod : 11:21 am

Service Requests:

Category Summary	Parts	Labor	Job Total
OIL CHANGES	\$66.30	\$29.95	\$96.25
TIRE SERVICE	\$595.00	\$49.95	\$644.95
USED CAR INSPECTION	\$0.00	\$157.50	\$157.50

Technician	Service Description	Parts	Labor	Job Total	
425	Used Car Inspection		157.50	157.50	
425	4 Tires Mount & Balance.	595.00	49.95	644.95	
	Section 30-20-1403, Colorado revised statutes requires retailers to collect a waste tire fee set by the solid and hazardous waste commission on the sale of each new motor vehicle tire and each new trailer tire				
	<u>Part Number</u>	<u>Part Description</u>	<u>Part Price Each</u>	<u>Quantity</u>	<u>Extended</u>
S	R502SB	18*8.5 SATEEN BLACK	148.75	4	595.00
425	5W30 Synthetic Full Service Oil Change		66.30	29.95	96.25
	<u>Part Number</u>	<u>Part Description</u>	<u>Part Price Each</u>	<u>Quantity</u>	<u>Extended</u>
	SYN 5W30	CASTROL EDGE SYN 5W30	7.77	6.9	53.61
N	276 180 00 09	OIL FILTER KIT W/ O-	12.69	1	12.69

Payments:

(On Account), \$923.26, on 01/15/19





1207 S. Platte River Dr.
Denver, CO 80223

(720) 398-6070

Invoice #:0022398

Original Estimate #:

AUTOMOTIVE IMPORTS

1207 S PLATTE RIVER DR

DENVER, CO 80223-

Home:(720) 398-6070

2015 Mercedes Benz CIs400

V6-2996 3.0L DOHC

VIN : WDDLJ6HB7FA156533

Mileage In 51015 Out 51081

Trans :

License : 0

Colr :

Prod :

1/15/19

11:21 am

Technician	Service Description	Parts	Labor	Job Total
	Unibody - GOOD			
	Grille - headlights, fog, trim - GOOD			
	Front bumper - fascia, guard, trim, paint - GOOD			
	Rear bumper - fascia, guards, trim, paint - GOOD			
	All body panels - GOOD			
	Windshield/glass - cracks, chips, scratch, pitting - MARGINAL - cracked			
	Nearest scheduled maintenance due if needed - GOOD			
	Wheels/rims - check for damage - GOOD			
	Headlights (high/low, aim) - GOOD			
	Front doors - controls, trim condition - GOOD - sm ding below handle			
	Rear doors/quarter trim - controls, trim condition - GOOD			
	Starting/Starter Operation - GOOD			
	Idle Vibration (cold/hot) - GOOD			
	Engine noise (cold/hot & high/low speeds) - GOOD			
	Driveability (smoothness) - GOOD			
	AT shift quality/AT shift problems - GOOD			
	MT shifter operations - GOOD			
	MT clutch (smoothness, effort, slippage) - N/A			
	Transmission/Transaxle noise (cold/hot) - GOOD			
	CV joint/drive axle noise (full lock turn R/L) - GOOD			
	Braking (noise, vibration, effort) - GOOD			
	Parking brake operation - GOOD			
	Steering effort (drifting right or left) - GOOD			
	Steering wheel free play/steering wheel centered - GOOD			
	Steering wheel - check damage - GOOD			
	Cruise control operation (include resume) - GOOD			
	Horn operation - GOOD			
	Wind noise/squeaks/rattles - GOOD			
	Speedometer/odometer operation - GOOD			
	Heater/defroster operation - GOOD			
	AC cooling performance/vent outlet temp - GOOD			
	Tire or steering wheel vibration - GOOD			
	Body/suspension (performance/noise/road test) - GOOD			
	Battery (condition, fluid level, load test) - GOOD			
	Alternator (belt, tension, charging) - GOOD			
	Water pump (noise, leaks) - GOOD			
	Distributor (cap&rotor condition, shaft) - N/A			
	Fuel system operation & fuel tank cap (leaks) - GOOD			
	Fuel filter - GOOD			
	Radiator (leaks, road hazard damage) - GOOD			
	Coolant recovery tank - GOOD			
	Cooling fan operation - GOOD			
	Coolant - GOOD			
	Coolant hoses (check condition) - GOOD			
	AC condenser (corrosion, damage) - GOOD			
	Power Steering Fluid - N/A			
	AC Compressor - GOOD			
	Engine/transmission mount - GOOD			
	Engine condition - GOOD			
	Timing belt condition (if accessible) - N/A			
	Brake master cylinder and booster - GOOD			
	Splash shields/underbody - GOOD			
	Valve stem condition - GOOD			
	Wheel lug nuts (all present & proper torque) - GOOD			
	Spare tire (condition/pressure) - GOOD			
	Transmission leaks - GOOD			
	Coolant leaks - GOOD			
	CV joint, boot, driveshaft - GOOD			
	Brake pad thickness - GOOD - 6-7			
	Brake rotor thickness & surface - GOOD			
	Tire Check Suggestions - Alignment			
	Front Tire Pressure - Checked-PSI			
	Rear Tire Pressure - Checked-PSI			
	Average Tread Depth - Checked - 5			
	Tire Wear Patterns - OK			
	Brake Calipers - GOOD			
	Rear Lining Thickness - N/A			
	Rear wheel cylinder leaks - N/A			
	Rear drum thickness/surface - N/A			
	Hydraulic hose/line leakage - GOOD			
	Suspension - GOOD			
	Strut/shock absorber leakage - GOOD			
	Bushing condition - GOOD			
	Ball joint & tie rod end wear - GOOD			
	Power steering rack leakage - N/A			
	Entire exhaust system - GOOD			
	Brake lights - GOOD			
	Turn signal lights - GOOD			
	Parking lamps - GOOD			
	Fog lamps - GOOD			
	Running lights - GOOD			
	License plate lights - GOOD			
	Tail lights - GOOD			
	Back up lamps - GOOD			
	Emergency flasher - GOOD			
	Water leaks (evidence of intrusion) - GOOD			
	Fuel gauge operation - GOOD			
	Temperature gauge operation - GOOD			
	Warning lights illuminated - GOOD			
	Dash light operation - GOOD			
	Windshield wiper/washer operation - GOOD			
	Audio system-radio, CD, cassette, speakers - GOOD			
	Clock functions - GOOD			
	Steering wheel tilt/lock - GOOD			
	Sunroof operation - GOOD			
	Headliner condition - GOOD			
	Cigarette lighter/power outlets - GOOD			
	Alarm/theft system operation - GOOD			
	SRS air bags - GOOD			
	Outside mirror operation (day/night function) - GOOD			
	Rear view mirror (day/night function) - GOOD			
	Window operation - noise, speed & full travel - GOOD			
	Door locks - maual/power operation/child lock - GOOD			
	Seat belts - condition/latching/retraction - GOOD			
	Seat upholstery/leather condition - GOOD			
	Power seat operation - GOOD			
	Seat heaters - GOOD			
	Headrest movement - GOOD			
	Rear defrost operation - GOOD			
	Interior mirror/vanity light operation - GOOD			
	Interior lights - switch/door/chimes - GOOD			
	Glove box - light operation - GOOD			
	Luggage compartment - jack/tool present - GOOD			
	Trunk lid release/light operation - GOOD			
	Fuel door release - GOOD			
	Hood release operation - GOOD			
	Check for dent, dings, scratches on interior panels - GOOD			
	Dash & instrument panels, carpet/mat stains - GOOD			
	Console/center arm rest/cup holders - GOOD			
	Luggage compartment - mat/trim/carpet - GOOD			
	Service Oil Change Light - Reset			
	Check for open recalls - GOOD			
	Tech notes - Checked			





1207 S. Platte River Dr.
Denver, CO 80223

(720) 398-6070

Invoice #:0022398

Original Estimate #:

AUTOMOTIVE IMPORTS

1207 S PLATTE RIVER DR
DENVER, CO 80223-
Home:(720) 398-6070

2015 Mercedes Benz C1s400

V6-2996 3.0L DOHC
VIN : WDDLJ6HB7FA156533
Mileage In 51015 Out 51081
Trans :
License : 0
Colr : **1/15/19**
Prod : 11:21 am

Technician	Service Description	Parts	Labor	Job Total
------------	---------------------	-------	-------	-----------

Repair Order Notes

WARRANTY INFORMATION

All other products and workmanship are warranted for 6 months or 6000 miles from the date of installation. All parts shown are new unless otherwise specified. I hereby authorize you and/or your agents to contact me regarding the products and services provided. An express mechanic's lien is hereby granted. I acknowledge receipt of a copy of this repair order.

Thank you for your business!

Questions or comments? Call us at 720-398-6070.

Visit us online at www.automotive-imports.com

Customer Signature: _____ Date: _____

TOTAL PARTS	\$661.30
TOTAL LABOR	\$237.40
SUBLET	\$0.00
SHOP SUPPLIES	\$24.56
SUBTOTAL	\$923.26
OTHER FEES	\$0.00
SALES TAX	\$0.00
TOTAL INVOICE	\$923.26
PAID	\$0.00
DUE	\$923.26

